

Quick Outlet Wiring Checks and Ground Fault Indication Testing



ERT100:

- Test and display wiring conditions of 110V AC outlets
- Rubber over molding for better grip
- cULus listed



ERT200:

- Test and display wiring conditions of 110V AC outlets
- Designed for GFI outlet with ground fault button (6 to 7mA)
- Rubber over molding for better grip
- cULus listed



Contact:
Industrial Process Measurement, Inc.
3910 Park Avenue, Unit 7
Edison, NJ 08820
732-632-6400
support@instrumentation2000.com
http://www.instrumentation2000.com



Made in CHINA

ERT200 0 53533 50759 1