



Rugged and reliable

Standard three-pin connector – Use with many widely available probes or order from our selection

All push-button operation - For fast, easy use

Ergonomic design – Easy to grip for onehanded operation

°C/°F selectable

Minimum and maximum temperature display – Displays highest/lowest temperature since meter was switched on, or use Min/Max Hold Mode to continuously update lowest/ highest temperature

Temperature offset calibration adjustment – Push-button adjustment for fine-tuning factory calibration

Hold function – Freezes measurements for convenient reading and recording

Auto-off function – Turns off meter after 17 minutes of nonuse to save batteries

Sealed keypad and ABS plastic case – Meet IP54 standards for splash resistance

Available protective rubber armor – Protects meter and features a built-in stand



General



Educational

Select a probe to match your

See page 82 for our wide selection of probes.

application



Specifications

Range: -200 to 850°C (-328 to 1562°F)

Resolution: 1°C/F from -200 to -100°C (-328 to -148°F) and 200 to 850°C (392 to 1562°F); 0.1°C/F from -100 to 200°C (-148 to 392°F)

Accuracy

From -200 to -100°C (-328 to -148°F): ±2°C/±4°F, From -99.9 to 199.9°C (-148 to 392°F): ±2°C/±4°F, From 200 to 850°C (392 to 1562°F): ±2°C/±4°F

Display: 4-digit LCD, $2\frac{1}{2}$ " x $1\frac{1}{2}$ " (5.7 x 3.8 cm) backlit viewing area

Probe: one 100 Ω platinum RTD with three-pin DIN connector (not included)

35426-20 shown with available rubber armor

Power: three AA batteries (included)

Battery life: 400 hours continuous (without the use of backlighting)

Dimensions (W x H x D):

Meter: 4" x 7" x 2" (10.2 x 18 x 5.2 cm) (with protective amor)

Boxed: 5%" x 101/4" x 3" (13.5 x 26 x 7.5 cm)

Weight: Meter: 0.75 lb (0.4 kg); Boxed: 1.25 lb (0.6 kg)





Ordering Information

Catalog number	Description	Included
WD-35426-20	Temp 16	Meter and batteries
WD-35426-21	Calibrated Temp 16	Meter and NIST-traceable calibration report
WD-35426-22	Calibrated system	Meter and NIST-traceable calibration report; probe sold separately
WD-35427-80	Rubber armor	Rubber armor with built-in meter stand
WD-35427-85	Hands-free kit	Multipurpose hanging strap and mounting magnets