

TECHNICAL DATA

Features

- Measures ambient temperature and relative humidity
- Designed for one-handed operation
- Backlit dual LCD display
- User selectable °F/°C
- Max, min and data hold functions
- Low battery indicator and auto shut off
- Includes batteries

Specifications

Temperature

Measuring Range: 14 to 140°F (-10 to 60°C)
Accuracy: ±2.0°F (1.0°C)
Resolution: 0.1°F/°C

Humidity

Measuring Range: 0 to 100% RH
Accuracy: ±5% RH
Resolution: 0.1% RH

General Specifications

Display: Dual LCD
Backlit Display: Yes
Data Hold: Yes
Max: Yes
Min: Yes
Sampling Rate: 1 time/sec.
Overrange Indicator: Yes
Auto Shut-off: Yes (after 5 mins, off)
Low Battery Indicator: Yes
Power Supply: 3 AAA Batteries
Product Certifications: CE
Operating Temperature: 32 to 122°F (0 to 50°C)
Storage Temperature: 14 to 140°F (-10 to 60°C)
Operating Humidity Range: 10 to 80%
Dimensions: 6.3 x 2 x 1.1"
(155 x 50 x 28mm)
Weight: 4.2 oz (102g)



Model	Description
R1910	Temperature & Humidity Meter
CA-52A	Soft Carrying Case